



Industrie Service

**Choose certainty.  
Add value.**

TÜV SÜD Industrie Service GmbH · 80684 München · Germany

## CDM Executive Board

Your reference/letter of	Our reference/name	Tel. extension/E-mail	Fax extension	Date/Document	Page
	IS-USC-MUC/Bb Werner Betzenbichler	+49-89 5791-2170 Werner.Betzenbichler@tuev-sued.de	+49-89 5791-2756	2006-09-11	1 of 2

### Request for review

Dear Sirs,

Please find below the response to the request for review formulated for the CDM project with the registration number 198. In case you have any further inquiries please let us know as we kindly assist you.

Yours sincerely,

Werner Betzenbichler  
Carbon Management Service

Michael Rumberg

## **Response to the CDM Executive Board**

### **Issue 1:**

There is no activity data in the monitoring report, only theoretical description of methodologies and description of some calculations. The section “Presentation of monitoring results-spreadsheets” says that all monitoring data have been included in an Excel workbook. In the section of monitoring report –“Calculation methodology” there is reference to Annex 2 but no explanation where this Annex is. No excel sheets or other type of Annexes with activity data or calculations are attached to the monitoring reports submitted and posted on the web.

### **Response by TÜV SÜD:**

The excel spreadsheet has been submitted in the course of the verification but the project participants have considered this document rather confidential as there is no such guidance on the extent of monitoring reports. Responding to this request the client accepted the publication of the data sheet attached (see response by the project participant).

### **Issue 2:**

In accordance with the Verification Report there should be a revised version of the Monitoring Report dated 2 August 2006, in which some CARs are already solved and particularly imported grid electricity consumption for calculation of net electricity (CAR #1) is added. The revised version posted on web is dated 20 July 2006 and the issue is not covered.

### **Response by TÜV SÜD:**

By ticking on the wrong file in the “explorer window” when uploading the documents TÜV SÜD uploaded twice the same file (Report version 20 July 2006). It was realized by TÜV SÜD some few days later and reported to UNFCCC secretariat some days before the request for review has been issued. As the wrong version was already made publicly available no correction is any longer possible besides this formal procedure. Meanwhile we have advised our personnel to check files more carefully when using the upload tools at the CDM webpages.