



## REVIEW OF THE PROJECT ACTIVITY

### “NorthWind Bangui Bay Project” (0453)”

At its fifty-first meeting the Board could not approve the request for issuance of CERs for the project activity “North Wind Bangui Bay Project ” (0453), submitted by the DOE (AENOR) for the monitoring period 26 August 2007 - 25 August 2008, because :

- (a) It has not been sufficiently demonstrated:
  - (i) how the formulae used by the project participant in calculating the electricity supplied to the grid by the project activity has been correctly applied, i.e. readings of the three meters used (M4, M8, and M9) are not reflected on the monitoring report or spreadsheet; and
  - (ii) whether the calculation of electricity supplied takes into account all sources of electricity imports from the grid to the project activity via both substations;
- (b) The DOE failed to request for deviation or revision of the monitoring plan, since the actual monitoring practice is not in accordance with the monitoring plan, i.e. additional meters were installed while the original monitoring plan requires the monitoring of electricity supplied to the grid by project by direct measurement.

- - - - -