



REVIEW OF THE PROJECT ACTIVITY

“Cimentos do Mozambique – Matola Gas Company Fuel Switch Project” (3048)

At its fifty-fifth meeting the Board could not register the project activity "Cimentos do Mozambique – Matola Gas Company Fuel Switch Project" (3048) as the project participants and the DOE (DNV) have failed to substantiate that the methodology has been correctly applied in line with the requirements of VVM version 1.1, paragraph 70, as:

- (i) The energy efficiency of the baseline is not measured in accordance with the methodology, and no request for deviation / clarification was submitted; and
- (ii) Monitoring of the efficiency of the project activity is not determined by undertaking measurements at the element process as per the requirement of the methodology.
