

DPM

## FAX MESSAGE

From: B.V.Ramanjaneyulu  
Dy. Manager/ES  
Camp: Bannari Amman Sugars


To: Sri T.Adishesan  
DGM / ES  
BHEL, R.C.Puram  
Hyderabad - 502032

Ref: BHEL/ES/BASL/01  
Date: 25-01-2001

FAX No: 040-3021911 / 3020214 / 3021920

Sub: Status of desalting of 16 MW Turbine - reg.


1. The Turbine was completely dismantled on 18-01-2001 (As Bolt heat equipment was not available with the customer, it was arranged by BHEL, Hyd on 20-01-2001) and all internals were cleaned by fine sand and broken rice blasting.
2. The re-assembly work is in progress. During assembly the top half of Balance Piston Gland at parting plane dia closed by 2 mm. All the internals except BP Gland are assembled and tack welded. We are not able assemble the BP Gland in distortion condition. Regarding this matter customer discussed with Sri Aravind Gupta and he suggested to send BP gland to our Hyderabad works for rectification.



3. We are held up for the final assembly. Please advise the course of action..

With regards.

  
(B.V.RAMANJANEYULU)  
25/01/01



77