



REVIEW OF THE PROJECT ACTIVITY

Eliane Natural Gas fuel switch project (1041)

The Board could not register the project activity, submitted for registration by the DOE (DNV Certification AS), because the project participant and the DOE failed to sufficiently substantiate that the monitoring requirements of ACM0009 version 3, in particular with respect to the monitoring of energy efficiency for the project activity, would be correctly applied in the project activity.