



REVIEW OF THE PROJECT ACTIVITY

Demand side energy efficiency project at IPCL-Vadodara Complex (0929)

The Board could not register the project activity submitted for registration by the DOE (BVC) because the DOE and project participant failed to substantiate that the applied methodology would be sufficient to allow adequate monitoring of the impacts of this project activity on the baseline scenario and therefore this particular methodology could not be considered to be applicable to the project activity.
